



UPPER MORELAND POLICE

Country Club Drive Speed Study May 2016

Initial Complaint:

A resident reported that vehicles speed at all times of the day on Country Club Drive.

Description of Area:

Country Club Drive is located in the Huntingdon Valley section of Upper Moreland Township. The roadway runs between Edge Hill Road and ends at the Huntingdon Valley Country Club. It is a local roadway in a residential neighborhood where homes line both sides of the roadway. The roadway is wide enough to accommodate on street parking on one side of the street. There are no sidewalks and the speed limit is 25 mph.

Data Gathering Method:

Speed/volume counters were placed on Country Club Drive for a period of seven days. Speed/volume counters were placed on Country Club Drive for a period of seven days displaying feedback.

Hazardous Factors:

Evaluating the speed of vehicles, the volume of traffic, and the total number of crashes assists in determining the level of response necessary to address the public safety concern.

During the first seven day period, the speed of vehicles using this section of Country Club Drive indicated that 0.78% of vehicles met the threshold for enforcement. The 85th percentile speed for vehicles on this section of Country Club Drive is 24.53 mph.

During the study period, 1,533 vehicles traveled on this section of Country Club Drive.

During the second seven day period, the speed of vehicles using this section of Country Club Drive indicated that 0.82% of vehicles met the threshold for enforcement. The 85th percentile speed for vehicles on this section of Country Club Drive is 24.04 mph.

During the study period, 1,947 vehicles traveled on this section of Country Club Drive.

Crash reports do not indicate that there is an existing public safety hazard on this section of roadway.



UPPER MORELAND POLICE

Analysis:

At this time, speeding is not an issue on this section of Country Club Drive. The average speed is 21.22 and 21.21 mph, respectively.

Response:

This location does not require enhanced patrol at this time.